

Jens Pind Linkage (JPL)

The AR for JPL is critical and should be around 3. If it is too loose, then the rings slip around each other and will not hold the weave.



1. Connect three rings together, each one linked through the other two. Add a marker ring (recommended but not essential) to mark the start of the chain. The rings are coloured to emphasise the orientation. Note that if you look end on to the copper ring, the rings are going anti-clockwise.



2. Add a ring (silver) through the previous two rings (gold and copper) in the same orientation as (i.e. parallel to) the first (silver) ring, ie. the one with the marker ring and continuing in the same direction of twist. Note that here the new silver ring is in front of the previous one. Each subsequent silver ring must be added on the same side to form a step effect when the chain is completed.



3. Add a new ring through the previous two rings in the same orientation as the third ring back

noting here that the new ring is below the previous one.



4. Again, add a new ring through the previous two in the same orientation as the third ring back noting that it is behind the parallel ring.



5. ...and again. You can see the step pattern developing now.



6. Continue adding new rings in the same way until the chain is the required length.

